

5. RECOMMENDED PACKAGING CONDITIONS AND HANDLING NOTES

PPMC-111C/CFP

5. RECOMMENDED PACKAGING CONDITIONS AND HANDLING NOTES

PPMC-111 comes in two package types, namely, PPMC-111C, which is a lead insertion type, and PPMC-111CFP, which is a surface mounting type. In mounting on the printed circuit board, the biggest problems that affect the reliability of PPMC-111 are contamination by flux and thermal stress during package soldering. Explained in this section are the recommended temperature profiles and general notes to be observed in mounting the PPMC-111.

5 - 1 Temperature profile

5 - 1 - 1 Soldering iron

(1) The temperature at the lead must be kept at 260°C for no longer than 10 seconds or 350°C for no longer than 3 seconds.

5 - 1 - 2 Far and medium-infrared reflow soldering

(1) Upper and lower heating by far- and medium-infrared reflow soldering is recommended.

(2) The temperature must be kept at not less than 210°C for 30 seconds or less while the package surface temperature must not go above 240°C. A recommended temperature profile is shown in Fig. 5-1.

(3) Note that near-infrared reflow soldering produces thermal stress similar to that of dip soldering.




Fig. 5-1 (Temperature Profile)

5 - 1 - 3 Case of hot air reflow soldering

(1) The temperature must be kept at not less than 210°C for 30 seconds or less while the package surface temperature must not go above 240°C.

(2) A recommended temperature profile is shown in Fig. 5-1.

5 - 1 - 4 Vapor phase reflow soldering

(1) The recommended solvent is Fluorinate FC-70 or the equivalent.

(2) The ambient temperature must be 215°C for no longer than 30 seconds or 200°C for no longer than 60 seconds.

(3) A recommended temperature profile for V.P.S. is shown in Fig. 5-2.

5. RECOMMENDED PACKAGING CONDITIONS AND HANDLING NOTES

PPMC-111C/CFP




Fig. 5-2 (Temperature Profile)

5-1-5 Dip soldering

- (1) Preheating must be done at 150°C for at least 60 seconds.
- (2) Solder flow must be done at a maximum temperature of 260°C for no longer than 10 seconds.

5-2 Flux cleaning (Ultrasonic cleaning)

- (1) Carry out flux cleaning in such a way that no reactive ions of Na or Cl remain. An organic solvent, if used, may react with water to produce some corrosive gas like hydrogen chloride, thus degrading the **PPMC-111** package.
- (2) Do not rub the marking with a brush or your hand during the cleaning or with the cleaning solution still on **PPMC-111**. Such careless operation may erase the marking.
- (3) In performing immersion cleaning, shower cleaning or steam cleaning, take great care in selecting the solvent to prevent unwanted reactions. The immersion time in solvent or steam should be 1 minute or less at a liquid temperature not exceeding 50°C.
- (4) For a highly efficient short-time ultrasonic cleaning, the following basic conditions are recommended:

Frequency	: 27kHz to 29kHz
Ultrasonic output	: 300W or below (0.25W/cm ² or below)
Cleaning time	: 30 seconds or less

Perform this cleaning with the package suspended in the solvent, taking care that the ultrasonic vibrator does not come into direct contact with the printed circuit board or **PPMC-111**.

5-3 Lead forming

In cutting or wave shaping prior to mounting **PPMC-111** on the printed circuit board, abnormal forces, if allowed to act on the inside of **PPMC-111**, may cause mechanical damage to it and lower its reliability. The main cause is the relative stress resulting between the **PPMC-111** body and the leads, which may damage the leads inside **PPMC-111**, disable close contact, or break the seal. When forming leads, therefore, observe the following instructions:

- (1) Design the printed circuit board in such a way that the intervals of the lead end insertion holes agree with the intervals of leads on **PPMC-111**.

5. **RECOMMENDED PACKAGING CONDITIONS AND HANDLING NOTES**

PPMC-111C/CFP

- (2) When they do not agree, never pull at or push the leads of **PPMC-111** to insert them into the holes in the printed circuit board.
- (3) Do not bring **PPMC-111** into close contact with the printed circuit board, but create a gap between them with a spacer or by lead forming.
- (4) Do not repeat bending and extending of leads.
- (5) The ends of lead pins are sharp so as to facilitate mounting. When you use your bare hands, therefore, take special care to avoid injuries (pricks) by the pin ends.
- (6) Observe the following points when carrying out lead forming beforehand:
 - a. Bend the lead by fixing the part closer to the mold of **PPMC-111**.
 - b. Make a space between the mold of **PPMC-111** and the fixing jig.
 - c. When bending along the fixing jig, take care that the edge of the jig does not damage the lead.

5 - 4 Coating of board

When your equipment requires high reliability or when it is used in an unfavorable environment (with humidity, corrosive gas, dust, etc.), consider the use of a damp-proof coating for the printed circuit board while taking into account the expected stress, the effect of impurities, etc.

There are a great variety of coating resins, and selection is generally made by experience. Therefore, in selecting your coating resin, make a close study of the thermal and mechanical stresses that may act on **PPMC-111**.

5 - 5 Degradation and breakdown by static charge

When handling **PPMC-111** alone, do it in an environment free from static electricity and wear antistatic clothing. Also, use antistatic material for the vessel or like object with which **PPMC-111** comes into contact and ground it through a protective resistance of 0.5Mohm to 1Mohm.

5 - 5 - 1 Control of working environment

- (1) As the humidity lowers in your working environment, human bodies and insulators may be more easily charged with static electricity through friction. The recommended humidity is therefore 40 to 60% with moisture absorption by **PPMC-111** taken into consideration.
- (2) Ground the equipment, jigs, etc. in the work area.
- (3) Provide some antistatic means, such as laying a conductive mat, on the floor of the work area and ground it.
- (4) Place a conductive mat on the work table to disperse static electricity and ground it. Never use a metallic surface for the work table which can cause a sudden charging at low resistance when a charged **PPMC-111** is brought into contact with it.
- (5) When automated equipment is used, observe the following instructions:
 - a. When the **PPMC-111** package is picked up with vacuum, provide an antistatic means, such as conductive rubber, on the end of the pickup arm.
 - b. Take care to minimize friction at the **PPMC-111** package surface. When friction can not be reduced structurally, make the frictional surface smaller, employ material with smaller friction coefficient or electrical resistance or use an ionizer.
 - c. Use a static extinguishing material for the part coming into contact with the lead terminals of **PPMC-111**.
 - d. Do not allow any charged body (clothing, body, etc.) to touch **PPMC-111**.

5. RECOMMENDED PACKAGING CONDITIONS AND HANDLING NOTES

PPMC-111C/CFP

- e. Do not allow the jigs used in the process to touch **PPMC-111**.
- f. Carry out ion neutralization by an ionizer in the process where the **PPMC-111** package can be charged.
- (6) Provide a VDT filter or other antistatic means on the surface of CRTs in the work area, and do not turn them on and off during operation as far as practicable. Otherwise electrical induction to **PPMC-111** may occur.
- (7) Cover the work chair with antistatic cloth and ground it with an earthing chain to the floor.
- (8) Place antistatic mats on the **PPMC-111** storage shelves.
- (9) Use static extinguishing material or antistatic material for the containers used for transportation or temporary storage of **PPMC-111s**.
- (10) Install antistatic grounding conductors in the static control area. You can also use the grounding conductor (Class 3) for transmission lines for this purpose, but do not share it with the grounding of other machinery.

5 - 5 - 2 Working notes

- (1) Have the workers wear antistatic clothing and conductive shoes.
- (2) Have the workers wear wrist straps which are grounded through a resistance of about 1Mohm.
- (3) Use a low-voltage type soldering iron and ground the end of it.
- (4) Use antistatic pincers that may come into contact with the lead terminals of **PPMC-111**, and avoid use of metallic pincers as far as practicable. Otherwise the charged **PPMC-111** may discharge suddenly at low resistance. When you use vacuum pincers, make certain that they have a conductive suction pad at the end and are grounded by antistatic earthing conductor.
- (5) Do not place **PPMC-111s** and their containers close to objects with strong electrical fields (e.g., CRT).
- (6) Place printed circuit boards with **PPMC-111s** on separate from each other in antistatic board containers. Also do not stack them touching each other. Frictional charging and discharging may occur.
- (7) Put on antistatic finger sacks or gloves as far as practicable when you have to touch **PPMC-111** directly.
- (8) Use an ionizer when wrist straps are not available or when **PPMC-111** is subject to friction.

5. RECOMMENDED PACKAGING CONDITIONS AND HANDLING NOTES

PPMC-111C/CFP

5 - 6 Requirements for service environment

5 - 6 - 1 Temperature environment

Generally speaking, semiconductor parts are more sensitive to temperature than other component parts. Since electrical characteristics can be restricted by operating temperatures, your design must take into account the temperature characteristics involved. Exceeding the specified operating temperature range may not only result in the loss of specified electric characteristics but also quicken the deterioration of **PPMC-111** and shorten its life.

5 - 6 - 2 Humidity environment

PPMC-111 is molded and thus does not provide perfect airtightness. Use in a high-humidity environment over a long period may allow the entry of moisture, which in turn may cause degradation and other troubles with the semiconductor chips inside. Therefore, apply a moisture-proof treatment to the surface of **PPMC-111**. In a low-humidity environment, damage may result from discharging of static electricity, so make certain that the humidity is in a range of 40 to 60% unless you take some antistatic measures.

5 - 6 - 3 Corrosive gas

PPMC-111 can react to some corrosive gases and suffer a drop in performance. For example, sulfuric gas from rubber near **PPMC-111** may corrode the lead terminals or cause a chemical reaction between lead terminals, thus forming foreign material there that will eventually cause leaks.

5 - 6 - 4 Radioactive rays / Cosmic rays

PPMC-111 is not designed for use with radioactive rays or cosmic rays. When it is used on space equipment or in an environment with radiation, it must be provided with a shield against the radioactive or cosmic rays.

5 - 6 - 5 Strong electric field / Strong magnetic field

If exposed to a strong electric field, the **PPMC-111** may develop abnormal phenomena, such as change in impedance or increase of leakage current, due to polarization inside its plastic materials or IC chips. In such applications, therefore, you need to provide a shield against the electric field / magnetic field. Especially in an AC magnetic environment, an appropriate magnetic shield must be installed against the electromotive force.

5 - 6 - 6 Vibration / Shock / Stress

The plastic-sealed **PPMC-111** has wire connections locked with resin inside, so that its structure has fairly strong resistance to vibration and shocks. In actuality, however, there can be cases of disconnection with vibration, shock or stress loosening the soldered parts. Therefore, do not use **PPMC-111** in equipment exposed to heavy vibration. Also, stress that bears on the semiconductor chips through the package may cause changes in resistance inside the chip due to a piezo-electric effect. Strong vibration, shock or stress may even crack the package or chips.

5 - 6 - 7 Dust / Oil

As with corrosive gas, **PPMC-111** can react chemically with dust or oil. Therefore, do not use **PPMC-111** in an environment where it may be exposed to dust or oil, which is capable of affecting its performance adversely.

5. RECOMMENDED PACKAGING CONDITIONS AND HANDLING NOTES

PPMC-111C/CFP

5 - 6 - 8 Smoking / Ignition

PPMC-111 is not incombustible, so it can smoke or burn, emitting toxic gas in the process. Therefore, do not use it near fire or other heat sources, ignitable or flammable substances.

5 - 7 Requirements for design

Observe the specified maximum ratings and recommended operating conditions for PPMC-111 so that it can achieve its design reliability for your system. Also, pay attention to such environmental conditions as ambient temperature, transient noise and surge to maximize the performance of PPMC-111.

5 - 7 - 1 Observance of maximum ratings

A maximum rating is a standard which must never be exceeded. This applies to all of the maximum ratings. There are maximum ratings for the voltage and current at individual lead terminals, the storage temperature, the lead terminal temperature, etc.

If the voltage or current at any of the lead terminals rises above the maximum rating, then the PPMC-111 may suffer degradation due to overvoltage or overcurrent. In extreme cases, wire may melt away or the semiconductor chip may break down from heat generated inside the internal circuit.

If the storage temperature or soldering temperature exceeds the rating, the differences in the coefficient of thermal expansion between materials in the PPMC-111 may cause the failure of airtightness or the opening of bonded joints.

5 - 7 - 2 Observance of guaranteed operation range

The recommended operating conditions guarantee the performance of PPMC-111.

5 - 7 - 3 Setting of unused I/O terminals

Unstable input may sometimes result from the use of PPMC-111 with unused input terminals in the open state. Also, output terminals must not be connected to the supply voltage (Vcc) or other output terminals.

As PPMC-111 with unused input terminals in the open state may be affected by external noise more easily and cause unstable operation, the input terminals should be pulled up to power supply (Vcc) or connected to the ground (GND) according to their functions.

5 - 7 - 4 Latch-Up

As PPMC-111 has a CMOS structure, a latch-up, in which a breakdown results from a large current of several hundred mA flowing between Vcc and GND, can occur.

A latch-up occurs when a large current flows to the internal elements as a result of an input/output voltage exceeding the rating or when the internal elements break down with the voltage at the power supply terminal (Vcc) exceeding the rating. In this case, even if the voltage above the rating is instantaneous, the PPMC-111 in a latch-up condition may retain the large current between Vcc and GND, thus causing heating or smoking. Therefore, be sure to observe the following instructions:

- (1) Do not raise the voltage at the I/O terminals above Vcc, and do not lower it below GND. The machine must be switched at a proper timing.
- (2) Do not allow abnormal noise to act on PPMC-111.
- (3) Fix the unused input terminals to Vcc or GND.
- (4) Do not short the output terminals together.

5. RECOMMENDED PACKAGING CONDITIONS AND HANDLING NOTES

PPMC-111C/CFP

5 - 7 - 5 Input/Output protection

Never use a wired logic connection, in which output terminals are interconnected, for **PPMC-111**, because it will short the outputs. Also, do not connect the output terminals directly to Vcc or GND.

5 - 7 - 6 Interface

When a device with I/O conditions different from those of **PPMC-111** is to be connected to **PPMC-111**, malfunction may result if there is disagreement in the levels of input V_{IL}/V_{IH} and output V_{OL}/V_{OH} .

5 - 7 - 7 External noise

When the signal lines of I/O signals to **PPMC-111** mounted on a printed circuit board are long, noise or a surge applied to **PPMC-111** from outside may cause malfunction or breakdown due to the overcurrent (overvoltage). Lower the signal line impedance or provide a noise removing circuit as protection against external noise. Also provide appropriate protective means against surges.

5 - 7 - 8 Other requirements

- (1) When designing your system, make certain that all fail-safe means are provided and aging and other necessary treatments are done on the component parts.
- (2) Do not place **PPMC-111** in a place with strong electric fields; otherwise charge-up may cause surface leaks and eventual malfunction. In such applications, protect the package surface with a conductive shield plate.
- (3) Make arrangement so that if some conductive material (metal pin, etc.) should drop onto the terminal of the **PPMC-111** on the board, it will not cause short-circuiting.
- (4) **PPMC-111** is not designed for use with systems whose failure or malfunction can directly threaten the lives of people or cause injuries to them (nuclear control, aircraft and space equipment, transportation equipment, combustion control, safety devices, etc.). If you apply **PPMC-111** to such systems, Ampere shall not be held responsible for any damages caused by such unwarranted use.