

PPMC-112

**Programmable Stepper
Motor Control LSI**

Rev.1-1

Ampere Inc.

PPMC-112

Programmable Stepper Motor Control LSI

Table of contents

1. SPECIFICATIONS AND FUNCTIONS	1-1
1-1. Description	1-1
1-2. Specification	1-2
1-3. Concepts and Performance of PPMC-112	1-3
1-3-1. Pulse rate and motor speed	1-3
1-3-2. Acceleration/ deceleration method	1-3
1-3-2-1. Linear acceleration/ deceleration method	1-3
1-3-2-2. S-shaped acceleration/ deceleration method	1-4
1-3-2-3. Free-curve acceleration/ deceleration method	1-4
1-4. Differences from PPMC series	1-4
1-4-1. Addition of serial communication mode	1-4
1-4-2. Support for interpolation function	1-5
1-4-3. Higher speed	1-5
1-4-4. Change in status register bit	1-5
1-4-5. True logic pulse output	1-5
1-4-6. Reduction of auxiliary I/O signals	1-5
1-4-7. Addition of interlock related command and signal	1-5
1-4-8. Current position read command	1-5
1-4-9. Addition of acceleration/ deceleration table read command	1-5
1-4-10. Addition of version code read command	1-5
1-4-11. Addition of pulse width setting command	1-5
1-4-12. Addition of error counter read command	1-5
1-5. Operational mode of PPMC-112	1-6
1-5-1. Parallel communication mode	1-6
1-5-2. Serial communication mode	1-6
2. TERMINAL ASSIGNMENT	2-1
2-1. Signal description of system hardware	2-7
2-1-1. RESET*	2-7
2-1-2. X1, X2 (Crystal oscillator)	2-7
2-1-3. MOD0, MOD1 (Operational mode set input)	2-8
2-1-4. PPMS* (SYNC-101 recognition input signal)	2-8
2-1-5. EXTCLK (External clock input)	2-8
2-1-6. CLK (4MHz clock output)	2-8
2-2. Host interface signals	2-8
2-2-1. CS* (Chip select)	2-8
2-2-2. A0 (Register select)	2-9
2-2-3. D7 - D0 (Data bus)	2-9
2-2-4. BUSC (Slave bus interface select)	2-9
2-2-5. DS*, WRS* (Data strobe, Write strobe)	2-9
2-2-6. R/W*, RDS (Read/Write, Read strobe)	2-9
2-2-7. INT* (Interrupt signal)	2-10
2-3. Serial Communication interface signals (Serial mode)	2-11
2-3-1. TXD, RXD (Transmit, Receive signal)	2-11

2-3-2. SEND (Send gate control signal output)	2-11
2-3-3. MOD0, MOD, MOD2 (Communication mode/ baud rate setting input)	2-11
2-3-4. DVADR0 to DVADR3 (Device address setting input)	2-11
2-3-5. HSP* (High speed polling mode assignment input signal)	2-12
2-4. Motor control signals	2-12
2-4-1. DIR (Rotation direction signal)	2-13
2-4-2. POUT (Pulse train output signal)	2-12
2-4-3. Pin1, Pin2 (Internal pulse counter input)	2-12
2-4-4. HOLD* (Motor hold signal)	2-13
2-4-5. RUN (Pulse output signal)	2-13
2-4-6. INTLK* (Interlock output start signal)	2-13
2-5. Limit and Alarm signals	2-14
2-5-1. ORG*, XORG*, YORG (Origin input signal)	2-14
2-5-2. FL*, BL*, FHL*, BHL* (Limit input signals)	2-14
2-5-3. ALM* (Alarm input signal)	2-16
2-6. SYNC-101 Control I/O signals	2-16
2-6-1. POUT - MRPLS (Master pulse)	2-16
2-6-2. CHGQ - CHGQ (Quadrant change signal)	2-16
2-6-3. AUXRST - AUXRST (SYNC-101 auxiliary reset signal)	2-16
2-6-4. AD0 - AD7, ALE, RD*, WR* (SYNC-101 control I/O bus)	2-16
2-7. Auxiliary input/ output signals	2-18
2-7-1. AUXIO - AUXI3 (Parallel) or AUXIO - AUXI5 (Serial)	2-18
2-7-2. AUXO0 - AUXO7 (Parallel) or AUXO0 - AUXO4 (Serial)	2-18
3. CONTROL COMMAND OF PPMC-112	3-1
3-1. PPMC-112 control command in parallel mode	3-1
3-1-1. Host interface register	3-5
3-1-1-1. Status register	3-5
3-1-1-2. Data register (at read)	3-7
3-1-1-3. Command register (write only)	3-7
3-1-1-4. Data register (at write)	3-8
3-1-2. Initialization commands	3-9
3-1-2-1. Initialization command for linear/ S-shaped acceleration/ deceleration method	3-10
3-1-2-2. Initialization command for free-curve acceleration/ deceleration method	3-13
3-1-3. Operation command	3-16
3-1-3-1. Emergency stop	3-17
3-1-3-2. Deceleration stop	3-18
3-1-3-3. Single step	3-19
3-1-3-4. Acceleration/ deceleration operation	3-20
3-1-3-5. Constant speed operation	3-22
3-1-3-6. Continuous constant speed operation	3-24
3-1-3-7. Continuous high speed operation	3-26
3-1-3-8. Constant speed origin search operation	3-28
3-1-3-9. Instantaneous speed change	3-30
3-1-3-10. Acceleration/ deceleration speed change	3-32
3-1-4. Auxiliary command (Internal register read command)	3-35
3-1-4-1. Finish status code read command	3-35
3-1-4-2. Error code read command	3-37
3-1-4-3. Current position read command	3-39
3-1-4-4. Auxiliary input signal status code read command	3-41
3-1-4-5. Control input signal status read command	3-42

3-1-4-6. Acceleration/ deceleration table read command	3-43
3-1-4-7. Version code read command	3-45
3-1-5. Auxiliary commands (Parameter data setting command)	3-46
3-1-5-1. Current position setting command	3-47
3-1-5-2. Auxiliary output command	3-49
3-1-5-3. High speed limit effective speed setting command	3-50
3-1-5-4. Interlock release position setting command	3-54
3-1-5-5. Pulse width setting command	3-56
3-1-6. SYNC-101 start up control command	3-57
3-2. PPMC-112 control command in serial mode	3-58
3-2-1. Communication protocol	3-58
3-2-2. Frame structure	3-59
3-2-2-1. 9 bit binary mode	3-59
3-2-3. 8 bit ASCII mode	3-59
3-2-3-1. The structure of control code	3-63
3-2-3-2. The structure of data section	3-64
3-2-3-3. Check sum calculation	3-64
3-2-3-4. Control protocol	3-64
3-2-3-5. Communication error prevention process	3-65
3-2-3-6. ASCII mode error control	3-65
3-2-4. SYNC-101 control command in ASCII mode	3-67
3-2-4-1. Circular interpolation operation command	3-67
3-2-4-2. Linear interpolation operation command	3-68
3-2-4-3. Single axis operation command	3-70
3-2-4-4. Current position reading command	3-70
3-2-4-5. Change in limit input	3-71
3-2-5. Difference in ASCII mode	3-71
3-2-5-1. Busy check command	3-72
3-2-5-2. Finish status code	3-73
3-2-5-3. Auxiliary I/O command	3-73
3-2-5-4. Error counter reading command	3-73
4. RATING	4-1
4-1. Absolute maximum ratings	4-1
4-2. DC Characteristics	4-1
4-3. AC Characteristics	4-2
4-3-1. RD and WR separate bus mode	4-2
4-3-2. DS and R/W bus mode	4-4
4-3-3. Alarm and limit signal input timing	4-6
4-4. Output drawing of PPMC-112	4-7
5. RECOMMENDED PACKAGING CONDITIONS AND HANDLING NOTES	5-1
5-1. Temperature profile	5-1
5-1-1. Soldering iron	5-1
5-1-2. Far and medium-infrared reflow soldering	5-1
5-1-3. Case of hot air reflow soldering	5-1
5-1-4. Vapor phase reflow soldering	5-1
5-1-5. Dip soldering	5-2
5-2. Flux cleaning (Ultrasonic cleaning)	5-2
5-3. Coating of board	5-2
5-4. Degradation and breakdown by static charge	5-3
5-4-1. Control of working environment	5-3

5-4-2. Working notes	5-3
5-5. Requirements for service environment	5-5
5-5-1. Temperature environment	5-5
5-5-2. Humidity environment	5-5
5-5-3. Corrosive gas	5-5
5-5-4. Radioactive rays/ Cosmic rays	5-5
5-5-5. Strong electric field/ Strong magnetic field	5-5
5-5-6. Vibration/ Shock/ Stress	5-5
5-5-7. Dust/ Oil	5-5
5-5-8. Smoking/ Ignition	5-6
5-6. Requirements for design	5-6
5-6-1. Observance of maximum ratings	5-6
5-6-2. Observance of guaranteed operation range	5-6
5-6-3. Setting of unused I/O terminals	5-6
5-6-4. Latch-Up	5-6
5-6-5. Input/ Output protection	5-7
5-6-6. Interface	5-7
5-6-7. External noise	5-7
5-6-8. Other requirement	5-7